



## Devil's Slide/Hwy 1 Storm Repair

Daily Updates from Bijan Sartipi



**Daily Update**  
July 14

### Repair Work

Devil's Slide (post mile 39.14)

- Level 'B' (lower level ocean side) – All 58 tie backs now installed as of July 13. Tie back stressing continued.
- Level 'D' (upper level cliff side) – Drilling for tie backs continued today from the bench. 31 of 33 now installed. Cable stressing continued.



Drilling at level D – south end of wall

### Retaining (micropile) Wall

- Drilling and driving steel piles continued today. 55 of 99 now installed.



Micropile drilling

### Rock Bolts Above The Road

- Drilling continued today to install 50 rock bolts above the level D bracing wall.

### Surface drains

- Installing surface drains below level B is well underway as can be seen from the photos below.

